US ERA ARCHIVE DOCUMENT

U.S. ENVIRONMENTAL PROTECTION AGENCY POLLUTION/SITUATION REPORT

Enbridge Pipeline Crude Release - Removal Polrep



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY Region V

Subject: POLREP #4

Enbridge Pipeline Crude Release

Z5JS

Marshall, MI

Latitude: 42.2395273 Longitude: -84.9662018

To: Brian Schlieger, U.S. EPA

Stephen Wolfe, U.S. EPA David Chung, U.S. EPA Jason El-Zein, U.S. EPA Mick Hans, U.S. EPA Jeff Kimble, USEPA Duty Officer, NRC John Maritote, U.S. EPA Carol Ropski, U.S. EPA

William Messenger, U.S. EPA ERB

Michael Chezik, US Department of Interior

Charles Gebien, US EPA
John Glover, US EPA
Beverly Kush, US EPA
Linda Nachowicz, US EPA
OSLTF USCG, USCG
Mark Horwitz, USEPA
Mark Durno, U.S. EPA
Jeff Kelley, USEPA

Sue Hauxwell, Calhoun County Public Health Joe Frost, Calhoun County Health Department

James Rutherford, Calhoun County Health Department

Connie Gibson, Calhoun County Sheriffs office

Cheryl Vosburg, City of Marshall Jill Slaght, 7th district of Michigan Ken Brock, 7th District of Michigan

Bruce Vanotteren, MDNRE

Brian Pierzina, PHMSA Central Region

Dan Capone, Weston Solutions

verneta simon, U.S. EPA

Thomas Hemminger, USCG Grand Haven

Ralph Dollhopf, US EPA James Saric, USEPA Dave Novak, U.S. EPA Region V

Ann Whelan, U.S. EPA Ronna Beckmann, U.S. EPA CAPT Stephen Torpey, USCG

Scott Corbin, Allegan County EMA Director

From: Ralph Dollhopf, On-Scene Coordinator

Stephen Wolfe, On-Scene Coordinator Jeffrey Kimble, On-Scene Coordinator

Date: 7/29/2010

Reporting Period: 7/28/2010 1800 hrs. 7/29/2010 1800

1. Introduction

1.1 Background

Site Number: Z5JS Contract Number: D.O. Number: Action Memo Date:

Response Authority: OPA **Response Type:** Emergency

Response Lead: PRP Incident Category: Removal Assessment

NPL Status: Non NPL Operable Unit:

Mobilization Date: 7/26/2010 **Start Date:** 7/26/2010

Demob Date: Completion Date:

CERCLIS ID: RCRIS ID:

ERNS No.: State Notification:

FPN#: E10527 Reimbursable Account #:



1.1.1 Incident Category

Emergency Response -- Pipeline Rupture

1.1.2 Site Description

A 30 inch pipeline ruptured releasing its contents (NRC report of 19,500 barrels) into a culvert leading to Talmadge Creek. Talmadge Creek leads to the Kalamazoo River. The site is along the River running from Marshall, Michigan to Battle Creek, Michigan. The River is bordered by marshland, residential properties, farm land, and commercial properties for the approximate 30 mile stretch of the affected river.

1.1.2.1 Location

Spill location origin is in Marshall, Michigan on Talmadge Creek and extends 30 miles down

the Kalamazoo River.

1.1.2.2 Description of Threat

Western Canadian crude oil was released from the pipeline and has entered a navigable waterway.

1.1.3 Preliminary Removal Assessment/Removal Site Inspection Results

Approximately 30 miles of the Kalamazoo River have been impacted. The Kalamazoo River level is higher than normal because of recent heavy rain in the area impacting boom deployment and site monitoring activities. The River levels are beginning to fall. Talmadge Creek has been boomed at the confluence to the Kalamazoo River and seem to be containing the oil still behind them. Boom has been placed in seventeen locations along the Kalamazoo River. Precautionary boom has also been deployed in Morrow Lake.

2. Current Activities

2.1 Operations Section

2.1.1 Narrative

2.1.2 Response Actions to Date

USEPA ERRS contactors have deployed 2,000 feet of boom. The RP has deployed boom and skimming equipment at seventeen locations along Talmage Creek and the Kalamazoo River. Recovered material is being temporarily stored in frac tanks on site. Tanker trucks are transporting the material to a facility owned by the RP with available storage in Griffith IN. To date approximately 2874 barrels of oil/water has been recovered Griffith IN. 16190 barrels has been collected and is being stored in frac tanks for future transport. No sheen has been observed on Morrow Lake to date.

START is monitoring air quality along the river and throughout residential areas. Monitoring equipment includes UltraRAE, PPB RAE, Multi RAE, Draeger CMS Chip Reader, and AreaRAE. The 51st Civil Support Team is providing air monitoring and sampling assistance by use of Hapsite portable GC/MS. The RP has contracted with CTEH to perform air monitoring services along the affected area.

US Fish and Wildlife Service is working with the wildlife team to address wildlife impacts. A rehabilitation center for oiled wildlife has been established and twenty three birds, mammals and turtles were brought in for cleaning.

The USCG Atlantic Strike Team is on scene to provide assistance with PRP and contractor oversight. Eight additional District 9 USCG staff arrived and were integrated into the response.

Several State Representatives and the Michigan Attourney General visited the site today.

NTSB and USDOT-PHMSA are on site conducting an investigation of the pipeline incident and are working with the appropriate State, Local, and Federal agencies.

Calhoun County Health Department in consultation with Michigan Department of Community Health and Agency for Toxic Substances and Disease Registry has issued a voluntary evacuation for several residences located immediately downstream of the spill site along the Talmedge Creek up to the confluence with the Kalamazoo River. This voluntary evacuation was based on review of air monitoring results for benzene around oil collection areas.

2.1.3 Enforcement Activities, Identity of Potentially Responsible Parties (PRPs)

Enbridge is the PRP.

On July 27, 2010, USEPA issued an Administrative Order under section 311(c) of the Clean Water Act to

Enbridge. Enbridge is actively addressing all the deliverables of the Order including but not limited to; drafting an overall site work plan; health and safety plan; and sampling and analysis plan.

2.1.4 Progress Metrics

Waste Stream	Medium	Quantity	Manifest #	Treatment	Disposal

2.2 Planning Section

2.2.1 Anticipated Activities

The RP is not planning to boom any additional sites but will augment the existing ones and work to collect more of the oil. USEPA contractors will continue deploying additional resources and setting boom.

Continue air monitoring and sampling at collection points, near residential areas and in response to odor complaints.

Collect water samples from Kalamazoo river upstream and downstream of Talmedge Creek.

2.2.2 Issues

The Kalamazoo River level is higher than normal because of recent heavy rain in the area impacting boom deployment and site monitoring activities. The water levels are falling.

RP has been informed that a Superfund site (PCB cleanup) is occurring on the Kalamazoo River Downstream of Morrow Lake (approximately 35 river miles downstream). The RP has been advised to make all efforts necessary to ensure the oil does not reach the Superfund Site. The City of Plainwell, Michigan has proposed a strategy involving boom diversion and oil collection as a contingency in the event oil impacts the Superfund Site.

2.3 Logistics Section

We are supporting twenty four hour operations.

Air monitoring support trailers are moving from the Enbridge Operations Center to the Walters Grade School.

Below is the equipment and staff deployed by Enbridge.

		Total
Employees	Enbridge	31
	Contractors	252
	Vacuum Trucks	45

	Skimmers	19
	Tanker Trucks	16
	Air Compressors	13
Major Bosouros	Light Plants	38
Major Resources	Trailers	11
	Trash Pumps	6
	Frac Tanks	64
	Boats	24
Longth of Room Donloved	Containment Boom (ft)	12,270
Length of Boom Deployed in River	Absorbent (ft)	8,240
III KIVEI	Total boom deployed	20,510
Length of Boom Available	Containment Boom (ft)	6,000
by River	Absorbent (ft)	
Length of Boom Available	Containment Boom (ft)	2,520
in Yard	Absorbent (ft)	
	Rate of Recovery (gph)	15,417
Total Recovery (oil &	Marshall (bbls)	19,460
water)	Griffith (bbls)	3,280

2.4 Finance Section

2.4.1 Narrative

The Oil Spill Liability Trust Fund has been accessed for U.S. EPA expenditures. FPN E10527. They are funding the response in two million dollar increments. At the current burn rate, we will need to request an increase in funding in ten days.

US Fish and Wildlife and the USCG have received a PRFA for their activities.

The RP is currently financing the cleanup operations.

2.5 Safety Officer

A 50 foot perimeter has been established as the hot zone around each vac truck. Personnel inside the area are wearing half face air purifying respirators due to benzene content. Workers in the area are using personal monitors for benzene.

US EPA is assisting the RP with drafting a site Specific Health and Safety Plan.

The Safety Officer visited several Divisions to monitor booming operations. The Safety Officer also took air monitoring readings at the Wildlife Rehabilitation Center at the request of Michigan Department of Agriculture. No significant VOCs were detected.

2.6 Liaison Officer

Approximately 30 State, Local, and Federal agencies are participating in the response.

2.7 Information Officer

2.7.1 Public Information Officer

The PIO

- Fielded several dozen calls from reporters in Michigan, Ontario, Washington D.C., and several other Great Lakes States
- Established elements of Joint Information Center with Michigan Agencies including the Governor's Office, Enbridge and Calhoun County Agencies
- Coordinated with EPA Headquarters Office of Public Affairs and EPA Region 5 Office of Public Affairs
- Coordinated a media briefing in Battle Creek, MI covered by 15-20 reporters both on-scene and by conference line.
- Initiated discussion of establishing a permanent media briefing location at a nearby location.

2.7.2 Community Involvement Coordinator

- Initiated planning for public meeting/availability session on Saturday afternoon at a nearby location.
- Held first briefing call with Michigan environmental groups to provide situation update.
- Assessed needs for ongoing public information in communities immediately affected by the spill.
- Fielded approximately a dozen calls forwarded by other parties in the response.

3. Participating Entities

3.1 Unified Command

Enbridge (Responsible Party)
US EPA
Michigan Department of Natural Resources and Environment
Michigan State Police Emergency Management Division
Calhoun County Public Health Department
Calhoun County Sheriff

3.2 Cooperating and Assisting Agencies

Cooperating Agencies

American Red Cross
Augusta Police Department
B&B Fire Safety Emergency Response
Calhoun Conservation District
Calhoun County Commissioners
Calhoun County Drain Commission
Calhoun County Sheriff's Office
Calhoun Conservation District
Calhoun Greenation District
City of Battle Creek, Michigan
City of Marshall, Michigan
Federal Energy Regulatory Commission
Fredonia Township Fire Department
Huron Potawatomi
Kalamazoo County Office of Emergency Management

Kalamazoo County Sheriff's Office Kalamazoo Public Safety Marshall Township Government and Fire Department Marshall Police Department Natural Resource Group National Transportation Safety Board Pipeline Hazardous Materials Safety Administration U.S. Department of Transportation U.S. Fish & Wildlife Service U.S. Department of Labor, OSHA

Congressional Presence

State Representative Jase Bolger State Representative Kate Segal State Representative Ken Kurtz State Representative Phil Browne State Representative Phyllis Browne State Representative Bob Geuctk State Representative Tanya Schuitmaker State Senator Mike Nofs U.S. Congressman Mark Schauer U.S. Senator Carl Levin U.S. Senator Stabenow

4. Personnel On Site

EPA OSCs	EPA IMT/RSC/MGMT	START
10	18	23

- 5. Definition of Terms
- 6. Additional sources of information
 - 6.1 Internet location of additional information/reports
 - **6.2 Reporting Schedule**
- 7. Situational Reference Materials